




file://A: M C-007 . G




file://A: M C-008 . G




file://A: M C-009 . G




01/09/2002




file://A: M C-011 . G








file://A: M C-013 . G 01/09/2002




file://A: M C-014 . G


Page 1 of 1




file://A: M C-015 . G




file://A: M C-016 · G



file://A: M C-017 . G 01/09/2002



file://A: M C-018 . G 01/09/2002







EXHIBIT Cappies.

Pictured below are the front and rear service manual covers for the Dean fryers with the prior art baffles. Note the rear cover as a date stamp of 5/87.

Front Cover



.

Rear Cover

Dean/ALCO

An Alco Foodservice Equipment Company

WARRANTY

Dean Industries warrants its products for a period of one (1) year on parts, Ninety (90) days on Labor from date of shipment, against defective material or work-manship, but not against damage caused by accident, abuse, faulty installation, or improper application or operation.

Ouring this period, Dean Industries will, at its option, repair or replace defective products returned, transportation charges prepaid, to its factory.


Dean Industries shall not be liable for any indirect or consequential damages. To the extent permitted by law, this warrantly is given in lieu of all other warrantles expressed or implied, and Dean Industries neither assumes nor authorizes any person to assume for it any liability beyond that stated herein. Factory approval must be obtained prior to any warranty work being done or Dean Industries cannot be held responsible.

Dean industries 5930 W. Jefferson Los Angeles, Calif. 90016

PIN 9059

464 5187

This exploded view drawing from the manual shows the use of the baffle in the fryer.






Solstice Series Fryers

Hot Results. Cooler Environment.




New, High Production, High Efficiency Solstice" Burner Design

> The Solstice™ burner draws more primary air for improved air/gas mixture. A new baffle design causes a "scrubbing action" of the flame which squeezes more heat out.* Since the baffle has more surface area than before, the baffle gets into radiant heating mode quicker for improved temperature recovery and faster cooking.



Self-Cooling Front Dack - Unique burner design draws cool air from the top deck

of cabinet for a cooler work environment and helps pre-heat the burner make-up air.



Easy to Own - Designed with insights from service techs. Smart design lowers cost of ownership."

Lower exhaust temperatures - Lower flue temperatures helps reduce **HVAC** cost.*

Recessed gas connection allows closer installation to the rear wall.

Faster Cooking - Up to 14.7% more cooking power than previous design. Faster cooking means less oil is absorbed by many products.


Stainless Steel Cabinet -Heavy gauge stainless steel front and sides are designed for long life and easy cleaning. Even the frver back can be ordered with a stainless steel panel.



Quality and Long Life

A new baffle design causes a "scrubbing action" of the flame which squeezes more heat out. Solstice fryers provide 13% - 17% more efficiency.*

Large cool zone minimizes costly oil breakdowns, carbonization, and taste transfer.



Pitco's 1-1/4" full port (I.D.) drains quickly and without clogging.

Fry tanks are completely pressure-blasted to clean and relieve stress at weld points, while smoothing surfaces for easier cleaning.

Tube-fired fryers require no extra insulation on the outside of the tank, making the fryer easier to service and eliminating the chance of capturing grease.



*As compared to the previous design